

# ALL IN ONE - Maintenance and Repair Manual - Edition 1 and 2 Correction to the tightening torque when screwing the brake calliper

Edition 1 and 2 of the ALL IN ONE Maintenance and Repair Manual have an error occurred at specify brake calliper torque. This information must be corrected in the already handed over editions.

## Affected pages of the ALL IN ONE Maintenance and Repair Manual:


- Edition 1 I 01.2018 I 703018040 Page 66
- Edition 2 I 04.2018 I 703018040 Page 70

#### Error

Rotation angle 90° at step 28 on the above announced pages.

## **Correction:**

Rotation angle 60° is correct.



We thank you in advance for your understanding and apologize for the inconvenience.

## Your gigant team

Created/inspected:	Released:
	25.06.2018 KK
26.06.2018 HU	25.06.2018 MG
Date Signature	Date Signature

gigant – Trenkamp & Gehle GmbH